

# Enger Golf Course

---

## Activities / Amenities

- Club House
- Driving Range
- Parking
- Golf Course (27 Holes)
- Portable Toilets

## Clubhouse

### Clubhouse

The Clubhouse was not included in the evaluation. There are plans to significantly alter the clubhouse. Note: there is not currently an accessible route into the clubhouse.



## Golf Course



### View of Golf Course / Putting Green

A hard surface route is provided throughout the golf course. There are no curbs that obstruct the route of golf cars. *This is a good example of accessibility.*



### Golf Cars

There are currently 60 golf cars available for rent. Currently none of the cars can be operated by hand controls.

### JQP, Inc. Recommends

**Priority 2-** Acquire a golf car that can be operated with hand controls.

### **Portable Toilets**

Staff indicated that 3 portable toilets are typically located on the course during the season (not provided at time of site visit). Staff indicated that larger/accessible portable toilets are not provided.

### **JQP, Inc. Recommends**

**Priority 2-** Provide a minimum of 1 accessible portable toilet on the course.

## **Driving Range**

### **Route**

An accessible route is currently provided from the parking lot to the driving range building and the tee boxes of the driving range. *This is a good example of accessibility.*



### **Building**

There are currently knobs used at 3 locations in the driving range building.

### **JQP, Inc. Recommends**

**Priority 3-** Replace the knob style hardware with a style that does not require any grasping, pinching or twisting of the wrist to operate (such as a lever).

ADA 309



### **Ball Machine**

There is a self-service machine for range golf balls. The collection area is currently on the floor, below the reach range (15"-48").

### **JQP, Inc. Recommends**

**Priority 3-** At such time the machine is replaced, ensure that all operable parts (money slot and collection point) are located within reach range.

ADA 308



## Parking



### **Quantity**

There is room for 135 vehicles in the parking lot, including 3 spaces designated as accessible. Based on the total number of parking spaces, a minimum of 5 accessible parking spaces are required.

### **JQP, Inc. Recommends**

**Priority 2-** Designate 2 additional accessible parking space. *ADA 208.2*

Note: JQP, Inc. only counted marked spaces within the lot, many course users park along the street near the club house and in the circle-drive.



### **Parking**

The designated accessible spaces are currently 8'-6" wide and do not provide an aisle.

The signs designating the accessible parking spaces are currently at 45" AFF.

### **JQP, Inc. Recommends**

**Priority 2-** Restripe the accessible parking spaces to provide an 8' wide minimum space with an 8' wide minimum aisle. (Note: 2 spaces can share an aisle.) *MN1341 502.4.2*

**Priority 3-** Raise the parking signs so the bottom edge is 60"-66" above the surface of the parking space. *MN1341 502.7*